

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: of _13 121243.021 1 Monitoring Well Soil Boring Project Number: 324460.1 East: Boring Location: North of Sunset Hills residential area North: 1569181.6 Elevation: 4341.6 feet amsl Drilling Contractor: WDC Driller: B. Zamow Date Started: 7/26/05 8/5/05 Date Finished: Total Water Depth: Drilling Equipment: Gus Pech GP24-400RS, Diedrich Sonic Head 22' / 19.49' 165.0 Depth: (feet) (feet) Well Diameter Sampling Method: Core Barrel Borehole Diameter: 6" 2-inch PVC and Material: Screened Interval Drilling Method: Sonic, utilized 6" casing and a 4.5" core barrel 100.6-120.6 ft., bottom at 120.8 ft. and Well Depth: Slot Size: **0.020''** Filter Material: #10-20 Silica Sand Well Seal: Bentontite and Cement Logged By: C. Gardner Swabbed, bailed, pumped Development Method: Graphic Log SCS Group Symbol Elevation (feet) Depth (feet) Sample No Lithology Sample Description Remarks Well Descriptions of drilled cuttings based LEAN CLAY (0-14 feet) Dry, hard, no odor. on ASTM Method D-2488 (the Primarily silt and clay with ~10% medium to fine sand and visual-manual procedure), grain-size trace coarse sand to ~3 mm. The sand is subangular to determinations and nomenclature based on the Unified Soil Classification subrounded. The fines have medium plasticity and toughness, are brown (10YR 4/3), and have a strong reaction System. Munsell colors described wet. 4340 Horizontal survey data is expressed in the Nevada State Plane system. Nevada West zone, in feet. Sharp contacts indicated by solid lines, gradational contacts indicated by dashed line. All depths are below land surface unless stated otherwise. 5 WELL DESIGN for B/W-10D: Screened Interval: 100.6-120.6 feet. Bottom of sump: 120.8 feet. SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 Cement Grout: 0-92 feet. 4335 Bentonite Chips: 92-96 feet. Filter Pack: #60 Sand 96-96.5 feet, #10-20 Sand 96.5-122.5 feet. Bentonite Chips: 122.5-165 feet Depth to Water Measuring Point is Top of PVC Casing. Top of PVC Elevation: 4,344.08 feet, PVC Stick-up: 2.5 feet above land surface.

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 2 of 13 ${f X}$ Soil Boring Monitoring Well Sheet Project Number: Graphic Log ISCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well 4330 SANDY LEAN CLAY (14-15.5 feet) CL Dry, hard, no odor. Primarily silt and clay with ~50% medium to fine sand and trace coarse sand to 4 mm. The sand is subangular to subrounded. The fines have medium plasticity and 15 toughness, are brown (10YR 5/3), and do not react to HCl. WELL-GRADED SAND with GRAVEL (15.5-17 feet) Moist to dry, loose, no odor. Primarily coarse to medium sand with ~20% fine gravel to ~15 mm and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are 4325 brown, and do not react to HCl. SM | SILTY SAND with GRAVEL (17-18 feet) Moist, medium dense, no odor. Primarily coarse to medium sand with ~40% gravel and ~25% silt and clay. The sand is subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. **SILTY SAND** (18-19.5 feet) Moist to dry, medium dense, no odor. Primarily medium to fine sand with ~15% coarse sand, ~5% fine gravel to ~8 mm, and ~15% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 **GRAVELLY LEAN CLAY with SAND** (19.5-20.5 feet) CL Moist, hard, no odor. 20 Primarily silt and clay with ~20% sand and ~30% gravel to ~25 mm. The sand and gravel are subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 4/3), and do not react to HCl. SM SILTY SAND with GRAVEL (20.5-21 feet) Dry, medium dense, no odor. Primarily medium to fine sand with ~20% gravel and ~20% SW silt and clay. The sand is subangular to subrounded, the gravel is subrounded. The fines have low plasticity and 4320 toughness, are brown, and do not react to HCl.

WELL-GRADED SAND (21-24.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with \sim 5% gravel to \sim 25 mm and \sim 5% silt and clay. The sand is subangular to subrounded, the gravel is subrounded to rounded. The fines are nonplastic, are brown, and do not react to HCl.

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 3 of 13 \mathbf{X} Monitoring Well Soil Boring Sheet Project Number: Graphic Log ISCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well WELL-GRADED SAND (24.5-25 feet) Saturated, medium dense, no odor. Primarily medium to fine sand to ~1.5 mm with trace silt and 25 SW clay. The sand is subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl.

WELL-GRADED SAND with GRAVEL (25-26 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with ~20% fine sand, ~35% gravel to ~30 mm, and trace silt and clay. The sand is subangular to subrounded, the gravel is subangular to rounded. The fines are nonplastic, are brown, and do not 4315 react to HCl. WELL-GRADED SAND with GRAVEL (26-27.5 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with ~35% gravel to ~30 mm and ~5% silt and clay. The sand is subangular to subrounded, the gravel is subangular to rounded. The fines are nonplastic, are light brown, and do not react to HCl. WELL-GRADED SAND (27.5-29.5 feet) ~ Saturated, medium dense, no odor. Primarily medium to fine sand with ~5% coarse sand to ~4 26 mm with trace silt and clay. The sand is subangular to B/W-10@ subrounded. The fines are nonplastic, are light brown, and do not react to HCl. GW-GM (29.5-30 feet) WELL-GRADED GRAVEL with SILT and SAND Saturated, medium dense, no odor. 30 Primarily gravel to ~20 mm with ~20% medium to fine sand, ~15% coarse sand, and ~10% silt and clay. The sand is subangular to subrounded, the gravel is subangular to rounded. The fines are nonplastic, are brown, and do not react to HCl. **SILT** (30-32 feet) Moist, soft, no odor. Primarily silt and clay with ~10% medium to fine sand to ~1 4310 mm. The sand is subangular to subrounded. The fines have low to medium plasticity and low toughness, are olive brown (2.5Y 4/3), and do not react to HCl. Some black organic SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 streaks LEAN CLAY (32-32.5 feet)
Dry to moist, stiff, no odor. ML Primarily silt and clay with ~10% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. **SILT** (32.5-33.5 feet) CL Moist, soft, no odor. Primarily silt and clay with ~10% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have low to medium plasticity and low toughness, are olive brown (2.5Y 4/3), and do not react to HCl. Some black organic streaks **LEAN CLAY** (33.5-35.5 feet) Dry to moist, stiff, no odor. 35 Primarily silt and clay with ~10% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. Some black organic streaks. **LEAN CLAY** (35.5-37.5 feet) Moist, very soft, no odor.

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 **4** of **13** \mathbf{X} Monitoring Well Soil Boring Sheet Project Number: Graphic Log SCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well Primarily silt and clay with \sim 20% medium to fine sand and trace coarse sand to \sim 3 mm. The sand is subangular to 4305 subrounded. The fines have medium plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. Some black organic streaks. CL SANDY LEAN CLAY (37.5-38.5 feet) Moist, stiff, no odor. Primarily silt and clay with ~30% medium to fine sand and trace fine gravel to ~15 mm. The sand and gravel are subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 5/3), and do not react to SW-HCl SM WELL-GRADED SAND with GRAVEL (38.5-40.5 feet) Saturated, loose, no odor. Primarily medium to fine sand with ~20% coarse sand, ~25% gravel to ~25 mm, and ~10% silt and clay. The sand is subangular to subrounded, the gravel is subangular to rounded. The fines are nonplastic, are brown, and do not react to HCl. 40 CL SANDY LEAN CLAY (40.5-41.5 feet) Moist, hard, no odor. Primarily silt and clay with ~35% medium to fine sand and trace coarse sand to ~4.5 mm. The sand is subangular to subrounded. The fines have medium plasticity and 4300 toughness, are brown (10YR 4/3), and do not react to HCl. SILTY SAND with GRAVEL (41.5-44.5 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with ~15% fine sand, ~15% gravel to 20 mm, and ~20% silt and clay. The sand and gravel are subangular to subrounded. The fines have low plasticity and toughness, are brown, and do not react to HCl. SILTY SAND with GRAVEL (44.5-48.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~15% coarse sand, ~15% 45 fine gravel to ~15 mm, and ~15% silt and clay. The sand SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. 4295 **SILTY SAND** (48.5-49 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~10% fine gravel to ~15 mm and ~20% silt and clay. The sand and gravel are

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 5 of 13 Soil Boring Monitoring Well Sheet Project Number: SCS Group Symbol Graphic Log Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well subangular to subrounded. The fines are nonplastic, and are WELL-GRADED SAND (49-55 feet) Saturated, medium dense, no odor. 50 Primarily medium to fine sand with ~5% gravel to ~25 mm with ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are light brown, and do not react to HCl. 4290 50 - 55 Ft B/W-10 55 WELL-GRADED SAND with SILT (55-58 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~5% fine gravel to ~15 mm and ~10% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. From 55-56.5 feet the interval has elongated gravel, from 56.5-58 the interval has no gravel. 4285 WELL-GRADED SAND with GRAVEL (58-59 feet) Saturated, medium dense no odor. SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 Primarily medium to fine sand with ~20% coarse sand, ~15% fine gravel to ~15 mm, and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are light brown, and do not react to HCl.

WELL-GRADED GRAVEL with SILT and SAND (59-60 feet) GM Saturated, medium dense, no odor. Primarily gravel to ~25 mm with ~15% medium to fine sand, ~15% coarse sand, and ~10% silt and clay. The sand is subangular to subrounded, the gravel is subangular to SW- rounded. The fines are nonplastic, are brown, and do not react to HCl. SM **SILTY SAND** (60-60.25 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~15% coarse sand, ~5% gravel to 20 mm, and ~20% silt and clay. The sand is subangular to subrounded, the gravel is subrounded to 4280 rounded. The fines are nonplastic, are reddish brown, and to not react to HCl. Red oxidized staining.

WELL-GRADED SAND with GRAVEL (60.25-63.5 feet) Saturated, medium dense, no odor.

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 6 of 13 \mathbf{X} Monitoring Well Soil Boring Sheet Project Number: Graphic Log SCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well Primarily medium to fine sand with ~15% gravel to ~25 mm and ~10% silt and clay. The sand is subangular to subrounded, the gravel is subangular to rounded. The fines are nonplastic, are brown, and do not react to HCl. No gravel in the interval from 61.5-63.5 WELL-GRADED SAND (63.5-64.5 feet) Saturated, loose, no odor. Primarily medium to fine sand with ~5% gravel to ~25 mm with trace silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. Some reddish brown iron oxide streaks at WELL-GRADED SAND (49-55 feet) 65 Saturated, medium dense, no odor. Primarily medium to fine sand with $\sim 10\%$ gravel to ~ 20 mm with trace silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. @ 64 - 69 Ft 4275 B/W-10 WELL-GRADED GRAVEL with SAND (67-69.5 feet) Saturated, medium dense, no odor. Primarily gravel to ~20 mm with ~15% coarse to medium sand and trace silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. **LEAN CLAY with SAND** (69.5-72 feet) Moist to saturated, loose, no odor. Primarily silt and clay with ~20% fine sand (<0.5 mm). The 70 sand is subrounded. The fines have low to medium plasticity and low toughness, are dark yellowish brown (10YR 4/4), and do not react to HCl. Interval has some reddish brown iron oxide streaks. SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 4270 POORLY-GRADED SAND with SILT (72-73.5 feet) SM Saturated, medium dense, no odor. Primarily medium to fine sand (<0.5 mm) with ~10% silt and clay. The sand is subangular to subrounded. The fines are nonplastic, are reddish brown, and do not react to HCl. **LEAN CLAY with SAND** (73.5-74.5 feet) CL Moist to saturated, soft to stiff, no odor. Primarily silt and clay with ~20% fine sand (<0.5 mm). The sand is subrounded. The fines have low to medium plasticity and low toughness, are olive brown (2.5Y 4/3), and do not react to HCl. SW-WELL-GRADED SAND with SILT (74.5-79 feet) Saturated, medium dense, no odor. Primarily medium to fine sand to ~2 mm with ~10% silt and clay. The sand is subangular to subrounded. The fines are

BORING LOG

B/W-10 Yerington Groundwater Investigation Well Number: Project Name: Monitoring Well 121243.021 7 of 13 ${f X}$ Soil Boring Project Number: Sheet ISCS Group Symbol Graphic Log Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well nonplastic, are brown, and do not react to HCl. <u>426</u>5 SW WELL-GRADED SAND with GRAVEL (79-84 feet)
Saturated, medium dense, no odor.
Primarily medium to fine sand with ~15% gravel to ~30 mm and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do 80 not react to HCl. 4260 WELL-GRADED SAND with SILT (84-87.5 feet) Saturated, medium dense, no odor. primarily medium to fine sand with trace fine gravel to ~10 mm and ~10% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 85 88 5 F B/W-10 @ 83.5 4255 SM **SILTY SAND** (87.5-89.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~25% coarse sand, trace fine gravel to ~10 mm, and ~15% silt and clay. The sand and gravel are subangular to subrounded. The fines are

BORING LOG

B/W-10 Yerington Groundwater Investigation Project Name: Well Number: 121243.021 **8** of **13** ${f X}$ Monitoring Well Soil Boring Project Number: Sheet SCS Group Symbol Graphic Log Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well nonplastic, are brown, and do not react to HCl. **LEAN CLAY with SAND** (89.5-92 feet) Moist, hard, no odor. Primarily silt and clay with $\sim 20\%$ fine sand (< 0.5 mm). The 90 sand is subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. Some black organic streaks. 4250 **LEAN CLAY with SAND** (94.5-95 feet) CL Moist, stiff to hard, no odor. Primarily silt and clay with ~20% medium to fine sand to ~1.5 mm. The sand is subangular to subrounded. The fines low to medium plasticity and low toughness in the upper and lower portions of the interval, medium plasticity and toughness in the middle portion of the interval, are brown (10YR 5/3), and do not react to HCl. Some black organic 95 4245 WELL-GRADED SAND (97-101 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel to ~10 YERINGTON.GPJ BRN&CALD.GDT 1/31/06 mm with ~5% silt and clay. The sand is subangular to subrounded, the gravel is subangular. The fines are nonplastic, are brown, and do not react to HCl. SONIC METHOD LOG WELL-GRADED SAND (101-102.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~5% gravel to ~20 mm

BORING LOG

B/W-10 Yerington Groundwater Investigation Project Name: Well Number: of <u>13</u> 121243.021 9 ${f X}$ Monitoring Well Soil Boring Project Number: Sheet SCS Group Symbol Graphic Log Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well with ~5% silt and clay. The sand is subangular to subrounded, the gravel is angular. The fines are nonplastic, B/W-10 @ 100 - 105 Ft are brown, and do not react to HCl. SW WELL-GRADED SAND (102.5-107 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with $\sim 10\%$ gravel to ~ 25 mm with ~5% silt and clay. The sand is subangular to subrounded, the gravel is angular to subangular. The fines are nonplastic, are brown, and do not react to HCl. 105 4235 **LEAN CLAY** (107-107.5 feet) Moist, stiff, no odor. Primarily silt and clay with ~10% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have medium plasticity and toughness, are dark grayish brown (10 YR 4/2), and do not react to HCl. WELL-GRADED SAND with SILT (107.5-115 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel to ~6 mm and ~10% silt and clay. The sand is subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. Increased grain size (includes ~15% angular to subrounded gravel to ~25 mm) between ~114 and 115 feet. 110-SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 4230

BORING LOG

B/W-10 Project Name: **Yerington Groundwater Investigation** Well Number: 121243.021 Sheet <u>10</u> of <u>13</u> \mathbf{X} Monitoring Well Soil Boring Project Number: Graphic Log ISCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well 115 WELL-GRADED GRAVEL with SILT and SAND GM (115-116.5 feet) Saturated, medium dense, no odor. Primarily gravel to 40 mm with $\sim 15\%$ sand and $\sim 10\%$ silt and clay. The sand is subangular to subrounded, the gravel is angular to rounded. The fines are nonplastic, are brown, and do not react to HCl. SW **WELL-GRADED SAND** (116.5-122.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. WELL-GRADED SAND with GRAVEL (119.5-121.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~15% gravel to ~30 mm 120 and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl. SW **WELL-GRADED SAND** (121.5-122.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel to ~6 120 - 125mm and ~5% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl.

WELL-GRADED SAND with GRAVEL (122.5-124 feet) B/W-10 Saturated, medium dense, no odor. Primarily medium to fine sand with ~15% coarse sand, ~20% gravel to ~30 mm, and ~5% silt and clay. The sand is subangular to subrounded, the gravel is angular to subrounded. The fines are nonplastic, are brown, and do not SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 react to HCl. WELL-GRADED SAND (124-124.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel to ~10 mm and ~5% silt and clay. The sand is subangular to subrounded, the gravel is angular to subangular. The fines 125 are nonplastic, are brown, and do not react to HCl. **WELL-GRADED SAND with SILT** (124.5-127.75 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with ~20% fine sand, trace fine gravel to ~9 mm, and ~10% silt and clay. The sand is subangular to subrounded, the gravel is angular to subrounded. The fines are nonplastic, are light brown, and do not react to HCl. 4215

BORING LOG

Proje	ect Nan	ne:	Yerington Groundwater Investigation			Well Number: B/W-10					
Soil Boring			Monitoring Well Number:			121243.021 Sheet 11 of					
	et)	/mbol			_	G	iraphi	c Log			
Depth (feet)	Elevation (feet)	USCS Group Symbol	Description	Sample No.	ort ordring	Sample	Lithology	Well		Remarks	
_		ML	SANDY SILT (127.75-128.5 feet) Moist, firm, no odor.								
130 —			Primarily silt and clay with ~30% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have low plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. SANDY LEAN CLAY (128.5-129.5 feet) Moist, stiff, no odor. Primarily silt and clay with ~30% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have								
	4210	ML	medium plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. SANDY SILT (129.5-130.5 feet) Moist, firm, no odor. Primarily silt and clay with ~30% medium to fine sand to ~1					2			
		CL	mm. The sand is subangular to subrounded. The fines have low plasticity and toughness, are brown (10YR 5/3), and do not react to HCl. LEAN CLAY (130.5-132 feet) Moist, hard, no odor. Primarily silt and clay with ~10% sand (<0.5 mm). The sand								
_		CM	is subangular to subrounded. The fines have medium plasticity and toughness, are light olive brown (2.5Y 5/3),								
-		SM	and have a strong reaction to HCl. SILTY SAND with GRAVEL (132-133 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~20% gravel to ~20 mm and ~25% silt and clay. The sand and gravel are angular to								
-	1		subangular. The fines have low plasticity and toughness, are brown, and to not react to HCl. LEAN CLAY (130.5-132 feet)								
-		SM	Moist, hard, no odor. Primarily silt and clay with ~10% sand (<0.5 mm). The sand is subangular to subrounded. The fines have medium plasticity and toughness, are light olive brown (2.5Y 5/3), and have a strong reaction to HCl.								
-	4205	SC	SILTY SAND with GRAVEL (132-133 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~20% gravel to ~20 mm								
135 -		CL	and ~25% silt and clay. The sand and gravel are angular to subangular. The fines have low plasticity and toughness, are brown, and to not react to HCl. CLAYEY SAND (134.5-135 feet) Moist to saturated, dense, no odor.								
-		SM	Primarily medium to fine sand with ~5% fine gravel to ~12 mm and ~35% silt and clay. The sand and gravel are angular to subangular. The fines have medium plasticity and					Z 5 6 8			
90)		SM	toughness and are brown. LEAN CLAY with SAND (135-136 feet)					<u>0</u> 70 64 14			
SONIC METHOD LOG YERINGTON GPJ BRN&CALD GDT 1/31/06 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		SW	Moist, hard, no odor. Primarily silt and clay with ~20% medium to fine sand to ~1.5 mm. The sand is subangular to subrounded. The fines have medium plasticity and toughness, are yellowish brown (10YR 5/4), and do not react to HCl.			•					
			SILTY SAND (136-136.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace fine gravel to ~8 mm and ~15% silt and clay. The sand is subangular to subrounded, the gravel is subrounded. The fines are	-		•					
YERINGTON			nonplastic, are brown, and do not react to HCl. SILTY SAND (136.5-137 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with ~5% fine gravel to ~10	-							
907 GOHL			mm and ~15% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, and do not react to HCl. WELL-GRADED SAND (137-145 feet)	1							
SONIC M.			Saturated, medium dense, no odor. Primarily coarse to medium sand with ~15% fine sand, ~5% gravel to ~30 mm, and ~5% silt and clay. The sand and	-							

BORING LOG

-	Yerington Groundwater Investigation		_ \	Vell Nu	mber: \mathbf{B}	S/W-10
Soil Boring	Monitoring Well X Project Nun	nber:	_		121243.02	1 Sheet 12 of 13
Depth (feet) Elevation (feet) USCS Group Symbol	Description	Sample No.	Sample	Graphic Fithology	Log	Remarks
$\mid \neg \mid \mid \mid$	gravel are subrounded. The fines are nonplastic, are brown, and do not react to HCl. The interval from 145-147.5 feet has ~15% gravel to 50 mm. The gravel is subrounded.	B/W-10 @ 140 - 145 Ft.				
-	WELL-GRADED SAND (145-147.5 feet) Saturated, medium dense, no odor. Primarily coarse to medium sand with ~15% fine sand, ~15% gravel to ~50 mm, and ~5% silt and clay. The sand and gravel are subrounded. The fines are nonplastic, are brown, and do not react to HCl.	-				
- GM	WELL-GRADED GRAVEL with SILT (147.5-149.5 feet) Saturated, dense, no odor. Primarily gravel to ~30 mm with ~10% coarse to medium sand and ~10% silt and clay. The sand is angular to subrounded, the gravel is subangular to subrounded. The fines are nonplastic, are dark brown, and do not react to HCl.	-				
150—	LEAN CLAY (149.5-151 feet) Dry to moist, hard, no odor. Primarily silt and clay with ~10% medium to fine sand to ~1 mm. The sand is subangular to subrounded. The fines have medium plasticity and toughness, are brown (10YR 4/3 to 10YR 5/3), and do not react to HCl.	-				
SM SMEHOD FOR JERNING	SILTY SAND (152-153.5 feet) Saturated, medium dense, no odor. Primarily medium to fine sand with trace coarse sand to ~4.5 mm and ~15% silt and clay. The sand is subangular to subrounded. The fines are nonplastic, are brown, and do not react to HCl.	-				
21 - 	<u>SILTY SAND</u> (153.5-154 feet)	1				

BORING LOG

Well Number: **B/W-10** Project Name: **Yerington Groundwater Investigation** 121243.021 Sheet <u>13</u> of <u>13</u> ${f X}$ Monitoring Well Soil Boring Project Number: Graphic Log ISCS Group Symbol Elevation (feet) Depth (feet) Sample No. Lithology Sample Description Remarks Well Saturated, dense, no odor. CL Primarily medium to fine sand with trace fine gravel to ~8 mm and ~20% silt and clay. The sand and gravel are angular to subangular. The fines are nonplastic, are brown, and do not react to HCl. SANDY LEAN CLAY (154-154.5 feet) 155 GW-Dry to moist, hard, no odor. GM Primarily silt and clay with ~20% coarse to medium sand and ~10% fine gravel to ~15 mm. The sand and gravel are GW- angular to subangular. The fines have medium plasticity and GM toughness, are yellowish brown (10YR 5/4), and have a strong reaction to HCl.

SILTY SAND with GRAVEL (154.5-155 feet) Saturated to moist, medium dense, no odor. 4185 Primarily coarse to medium sand with ~20% fine gravel to ~15 mm and ~15% silt and clay. The sand and gravel are angular to subangular. The fines are nonplastic, are yellowish brown, and have a strong reaction to HCl. WELL-GRADED GRAVEL with SILT and SAND (155-155.5 feet) Saturated, medium dense, no odor. Primarily gravel to ~75 mm with ~20% coarse to medium sand and ~10% silt and clay. The sand and gravel are subangular to subrounded. The fines are nonplastic, are olive brown, and have a strong reaction to HCl.

WELL-GRADED GRAVEL with SILT and SAND (155.5-160 feet) Saturated, medium dense, no odor. Primarily gravel to ~55 mm with ~25% coarse to medium sand and ~10% silt and clay. The sand is subangular to subrounded, the gravel is angular to subangular. The fines are nonplastic, are brown, and do not react to HCl. 160 CL **SANDY LEAN CLAY** (160-161.75 feet) Moist, stiff, no odor. Primarily silt and clay with ~30% sand and trace fine gravel to ~15 mm. The sand and gravel are subangular to subrounded. The fines have medium plasticity and toughness, are light yellowish brown (2.5Y 6/3), and have a strong reaction to HCl. 4180 CL SANDY LEAN CLAY (154-154.5 feet) Moist to dry from 161.75-162 feet, dry from 162-165 feet, very hard, no odor. Primarily silt and clay with ~35% coarse to medium sand and ~10% gravel to 20 mm. The sand and gravel are angular to subangular. The fines have medium plasticity and toughness, SONIC METHOD LOG YERINGTON.GPJ BRN&CALD.GDT 1/31/06 are yellowish brown (7.5YR 5/2), and have a strong reaction to HCl. 165